

STANDARD INFORMATION

Standard: UL 943B

Standard ID: Appliance Leakage-Current Interrupters [UL 943B:2026 Ed.4]

Previous Standard ID: Appliance Leakage-Current Interrupters [UL 943B:2017 Ed.3+R:10Jan2023]

EFFECTIVE DATE OF NEW/REVISED REQUIREMENTS

Effective Date: **April 29, 2028**

IMPACT, OVERVIEW, AND ACTION REQUIRED

Impact Statement: Per our accreditation, Intertek is required to review reports against the standard revisions to confirm compliance. Once compliance is confirmed, the standard reference in the report is updated to show continued compliance to the technical requirements of the standard. Reports not updated to this version by the effective date above will be withdrawn.

Overview of Changes: Additional requirements for the auto-monitoring function. Specific details of new/revised requirements are found in table below.

Current Listings Not Active? – Please immediately identify any current Listing Reports or products that are no longer active and should be removed from our records. We will do this at no charge as long as Intertek is notified in writing prior to the review of your reports.



STANDARD INFORMATION

CLAUSE	VERDICT	COMMENT
		<i>Additions to existing requirements are <u>underlined</u> and deletions are shown lined-out below.</i>
20	Ino	Auto-Monitoring Function
20.2		The auto-monitoring function shall perform the automatic test each time power becomes available to the line terminals. The automatic test shall be initiated <u>and meet the requirements of 20.4 with the simulated auto-monitor fault condition present</u> within five seconds of power applied to the line terminals. The automatic test shall be repeated at least every 15 minutes.