

STANDARD INFORMATION

Standard: CSA C22.2 No. 150

Standard ID: Microwave Ovens [CSA C22.2#150:2016 Ed.4+E1;U1;U2]

Previous Standard ID: Microwave Ovens [CSA C22.2#150:2016 Ed.4+E1;U1]

EFFECTIVE DATE OF NEW/REVISED REQUIREMENTS

Effective Date: **July 1, 2027**

IMPACT, OVERVIEW, AND ACTION REQUIRED

Impact Statement: Per our accreditation, Intertek is required to review reports against the standard revisions to confirm compliance. Once compliance is confirmed, the standard reference in the report is updated to show continued compliance to the technical requirements of the standard. Reports not updated to this version by the effective date above will be withdrawn.

Overview of Changes: Additional requirements for bottom-hinged doors. Specific details of new/revised requirements are found in table below.

Current Listings Not Active? – Please immediately identify any current Listing Reports or products that are no longer active and should be removed from our records. We will do this at no charge as long as Intertek is notified in writing prior to the review of your reports.



STANDARD INFORMATION

CLAUSE	VERDICT	COMMENT
		<i>Additions to existing requirements are <u>underlined</u> and deletions are shown lined-out below.</i>
5	Info	Construction
5.26	Info	Child-resistant oven door
		The requirements of Clause 5.26.1 shall not apply to the following product types:
5.26.3		a) over-the-cooktop or under-cabinet mounted ovens, provided the manufacturer's installation instructions is marked in accordance with Clause 6.6A; b) built-in or wall-mounted ovens, provided either: i) the manufacturer's installation instructions are marked in accordance with Clause 6.6B; ii) the product has a bottom-hinged door; or iii) the product is a drawer microwave; c) microwave ovens intended for commercial use only, and marked in accordance with Clause 6.5; and <u>d) household, countertop microwave ovens employing a bottom-hinged door, provided the manufacturer's installation instructions are in accordance with Clause 6.6B.</u>
5.26.4		An oven <u>employing a side-hinged door, or a bottom-hinged door, and not complying with the exception in Item d) in Clause 5.26.3, shall be</u> subjected to a force on the door handle per test procedure in Clauses 5.26.5 and 5.26.7. During this test, the door shall not open and the appliance shall not move on the test surface.
		<i>New clause added;</i>
5.26.4A		A countertop oven employing a bottom-hinged door, complying with the exception in Item d) in Clause 5.26.3, shall be subjected to a force on the door handle per the test procedure in Clauses 5.26.5 and 5.26.7. During this test, the door shall be opened to the maximum extension, and the appliance shall not tilt more than 10° in relation to the countertop.